

Oil Field Environmental Incident Summary

Incident: 20150522170548 **Date/Time of Notice:** 05/22/2015 17:05

Responsible Party: HESS CORPORATION

Well Operator: HESS CORPORATION

Well Name: BLDU D-310 Satellite Testing Facility

Field Name: BEAVER LODGE

Well File #:

Date Incident: 5/22/2015 **Time Incident:** 12:00

Facility ID Number: 400035-05

County: WILLIAMS

Twp: 156

Rng: 96

Sec: 35

Qtr: SW NE

Location Description:

Submitted By: Alex Beach

Received By:

Contact Person: Jason Henry
3015 16TH ST SW STE 20
MINOT, ND 58701

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1500 Feet

Distance Nearest Water Well: 1500 Feet

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|-------|---------|---------|-----------|---------|----------|-------|
| Oil | 120 | Barrels | 100 | Barrels | | |
| Brine | 25 | Barrels | | | | |
| Other | | | | | | |

Description of Other Released Contaminant:

Inspected:

Written Report Received: 7/14/2015

Clean Up Concluded: 6/26/2015

Risk Evaluation:

At this time there is no immediate risk suspected.

Areal Extent:

The release remained on site.

Potential Environmental Impacts:

The release impacted an estimated 3,960 sq. ft. of Well/Facility Soil. There are no other suspected environmental impacts at this time.

Action Taken or Planned:

A vacuum truck was dispatched to the site to begin removing the emulsion inside the tank berm. At this time 100 bbl of oil have been recovered from inside the tank berm. The tank berm failed on the North, East and South side, allowing some saltwater and oil to seep out. Another vacuum truck has been dispatched to the site to remove the standing emulsion outside of the tank berm and finish removing the remaining fluid inside the tank berm. The affected area outside of the tank berm consists of a 3,960 sq. ft. area all on location. A cleanup contractor is bringing in a small load of clay to berm up the South side of location to ensure the emulsion will remain secured onsite. The remaining impacts will be cleaned up and disposed of at an approved waste facility. An appropriate investigation will be scheduled. This site is part of a Lease Operate by Exception run, but this site is visited every day by the Lease Operator.

Wastes Disposal Location: The waste will be disposed of at an approved waste disposal facility.

Agencies Involved:**Updates**

Date: 5/26/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:**Updated Salt Water Volume:****Updated Other Volume:****Updated Other Contaminant****Notes:**

According to the incident summary, this spill remained on location within the diking. NDIC retains oversight.